



- Vacuum by mbars and time, or both.
- Gas injection by mbars and time over gas.
- Replaceable rings to adapt the tray to every manufacturer.
- Film progress mode: by length-by printed stain.